

## ATEX Directive 2014/34/EU

**Notes:**

Group I - Mining

Category M1 equipment can remain energised during a firedamp outbreak


Category M2 equipment must be de-energised during a firedamp outbreak

Group II - Surface industries

Category 1 equipment is suitable for Zone 0 (gases - 1G) or 20 (dusts - 1D)

Category 2 equipment is suitable for Zone 1 (gases - 2G) or 21 (dusts - 2D)

Category 3 equipment is suitable for Zone 2 (gases - 3G) or 22 (dusts - 3D)



NB - Unit Verification is optional for category 3 equipment